

Abstract

When a fuel pressure on the downstream side of a fuel pump for an internal combustion engine is less than a slice level, it is judged whether or not an applied voltage on a motor unit and/or the power consumption in the motor unit are normal. In the case where the motor unit is not failed, it is estimated that the pump unit is failed.